Notice



☐ CORRECTION ● PRODUCTION CHOOSE ☐ SERVICE FLASH ☐ ADD INFORMATION					
Please add this notice to the Service Ma	nual listed below. REVISION 0				
Category: COLOR TELEVISION	Date: JULY / 12 / 2011				
Model: DP32640	Effective from : Chassis No. P32640-07				
Destination: <u>U.S.A. / CANADA</u> REF : <u>No. SM780187-07</u>					
	t's back cover with the Chassis No. in the Service sis No. does not match the unit's, additional Service				

Model DP32640 (SM7800187).

Literature is required. This chassis is similar to Chassis No. P32640-05. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P32640-05 used in

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. 088 OP2 Data should be changed from 0Ah to 0Ch in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 18, Chassis Electrical Parts List	▲ EL901	Old	1AV4T40C18600	LCD(LC320WXN-SCB1)	1	NO	D
		New	1AV4T40C27100	LCD(T315XW03 V305)	1	NO	

For detailed panel (EL901) service differences refer to the following.

P26640-05 (OLD)

Part Number Description

▲ 86632L-0627A- INVERTER LC320WXN-SCB1 4T40C18600,LC320WXN-▲ 86871L-2058A- T-CON/PN LC320WXN-SCB1 4T40C18600,LC320WXN-

P26640-07 (NEW)

Part Number Description

▲ 819.31T08.006 40C27100,T315XW03 V3 INVERTER

© Sanyo Manufacturing Corporation 2011

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

July 2010 SMC